

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)

(Re: G.O. Ms. 20/70/PWD Dt.23-01-1970)

Name of the School

:All Saints Public School Chayam

1. Name of the Officer :Assistant Engineer,LID&EW Section,Tholicodu G P
2. Location : Attingal,Palode
3. Period for which the certificate is issued :2024-25
4. Types of Building : Details Over leaf
5. Nature of defect if any :Nil
 - a) Foundation and basement :
 - b) Superstructure :
 - c) Doors and windows :
 - d) Wood work wrought and put up :
 - e) Roof :
 - f) Flooring :
 - g) Miscellaneous (Cracks if any) :
6. Any Major defects notices which will render the buildings unsafe in any manner :
7. Whether maintenance works have been done properly : Yes
8. Whether the structure is sound or not for : Yes, sound for conducting classes
9. conducting classes

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certificate that the School was inspected by me on27/06/2024..... and found to be fit / unfit to conduct classes for the period2024-25..... for the reason stated above.

Place :Tholicodu.....

Date :...03/07/2024.....



Building Details

<u>Sl:No</u>	<u>Size</u>	<u>No</u>	<u>Purpose</u>	<u>Building Type</u>	-
1	6.096 x 6.096	7	Class Rooms	RCC Permenent	Cellar
2	6.096 x 6.096	8	Class Rooms	RCC Permenent	Ground Floor
3	6.096 x 6.096	1	Staff Room	RCC Permenent	
4	6.096 x 6.096	1	Office	RCC Permenent	
5	6.096 x 6.096	1	Principal Room	RCC Permenent	
6	6.096 x 3.048	1	Guest Room	RCC Permenent	
7	6.096 x 3.048	1	Knowledge Centre	RCC Permenent	
8	6.096x 9.144	1	Chemistry Lab	RCC Permenent	
9	6.096 x 9.144	1	Library	RCC Permenent	
10	6.096 x 6.096	9	Class Rooms	RCC Permenent	First Floor
11	6.096 x 18.288	1	Mini Auditorium	RCC Permenent	
12	6.096 x 9.144	1	Computer Lab	RCC Permenent	
13	6.096 x 9.144	1	Physics Lab	RCC Permenent	
14	6.096 x 6.096	9	Class Rooms	RCC Permenent	Second Floor
15	6.096 x 9.144	1	Biology Lab	RCC Permenent	
16	6.096 x 9.144	1	Media Room	RCC Permenent	